



Technical Service Bulletin

42 Rattle noise from rear suspension

42 17 37 2038689/2 April 18, 2017. Supersedes Technical Service Bulletin Group 42 number 14-22 dated December 10, 2014 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A6, A7	2014 - 2016	All	Not Applicable
A5, A5 cabriolet	2014 - 2018	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Added model years)
1	12/10/2014	Initial publication

Clunking or rattling noises are heard from rear suspension area when vehicle is driven over bumps.

Technical Background

These noises can be caused by an improperly seated rear bump stop (which occurs when the rear bump stop was not fully inserted into the rear shock absorber mounting during PDI).

Technical Service Bulletin

Production Solution

A bump stop installation tool (SET900) was developed to aid with the installation of rear bump stops on B8 and C7 vehicles during PDI (Figure 1). This tool provides the necessary leverage to seat the rear bump stop in the shock absorber mounting.



Tip: One SET900 tool was sent to all Audi dealers in November 2014. Additional tools can be purchased through the *Audi Special Tools and Equipment Program*.



Figure 1. The SET900 bump stop installation tool.

Service

To ensure proper installation of rear bump stops (in Audi models without air suspension):

1. Clean the top of the rear bump stops and coat with tire mounting paste.
2. Use the SET900 special tool to fully press the rear bump stops in to the upper shock mounts (Figure 2).

The purpose of the tool is to properly seat the rear bump stops in the rear shock mounts (Figure 3), which will prevent them from dropping out of the rear upper shock mounts and causing noise.



Figure 2. The SET900 tool being used to install a rear bump stop.

Technical Service Bulletin




Figure 3. Comparison between rear bump stop installation without and with the SET900 tool.



Note:

Always ensure that the dust boot does not get caught on the top of the shock once the vehicle is lowered.



Tip: A video demonstrating the use of this tool is available at:

<https://audi-external.kzoplatform.com:443/swf/player/286>

(Figure 4). See TSB 2039206 for more information about viewing videos.

Technical Service Bulletin



Figure 4. QR code for viewing the video with a QR code reader on phones and tablets. Alternatively, the video can be accessed through computer internet browsers at the link provided in this bulletin.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2039206, *00 Viewing TSB videos.*

All parts and service references provided in this TSB (2038689) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in



Technical Service Bulletin

any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.